



18



ACCESSORIES


NT DRILL CHUCK ARBOR



When ordering, please do clearly specify either Whit Or Metric DRAW BAR THREADS desired.

TYPE	D	d ₁	L	l ₁	l ₂	1/2" W12 or M12 x 1.75P 5/8" W11 or M16 x 2.0P
NT30 x JT6	49	31.75	111	68.4	18.6	
NT40 x JT6	63	44.45	138	93.4	20.6	

MILLING MACHINE ADAPTOR



When you are ordering this product, be sure to tell us the DRAW BAR SIZE you are going to use.

SIZE	l ₁	D	d ₁	d ₂	d ₃	d ₄	L	a	T
NT30 x MTA3	65	49	31.75	40	17.15	23.825	133.4	1.6	1/2" W12 M12 x 1.75P 5/8" W11 or M16 x 2.0P
NT40 x MTA3	65	63	44.45	40	25.07	23.825	158	1.6	